

Historic Preservation Commission OXFORD HISTORIC PRESERVATION COMMISSION MEETING MINUTES 18MAY2023

Date & Time:	18MAY2023 @ 6:04 pm
Location:	Oxford Town Hall, Meeting room

Meeting Details	□ Special Session⊠ Regular Meeting		
Attendees	AVEO PV Derreck Brown, Chair David Quinn, Vice Chair Lisa Schon, Secretary Dickon Housman, Treasurer Carla Pruett-DuBois, Member Lillie Armstrong, Member Jim Branch, Member Lillie Armstrong, Member Cheryl Hart, Oxford City Planning Office	Invitees Cynthia Scearce, COA Applicant James McCloud, COA Applicant Bill Coburn, COA Applicant Elim Malinowski, COA Applicant James Compton, COA Applicant	
Call to Order/Time	6:04 pm by Derreck Brown, Chair		
Attachments/Links	None		
Approval of Meeting Minutes	Date of Minutes: 02NOV, 10NOV2022 & 19JAN2023 Motion to Approve: Jim Brantley Second: Lisa Schon Outcome: 02NOV, 10NOV2022 & 19JAN2023 minutes approved		
Ethics and Conduct Statement	Read by: Carla Pruett-DuBois, Dickon Housman, Lillie Armstrong Commission Members understand and agree		
Lisa Schon, Secretary No conflicts were state	, provided the swearing in of the homeowners or repred.	resentatives for his/her COA presentation.	

COA # 1 Application Review					
Property Address: 400 College Street, Booth Watkins Mitchell House, Italianate- Circa 1880's Property Type: ⊠ Contributing Residential □ Non-Contributing Residential □ Commercial Sworn Stakeholders: Cynthia Scearce HPC Conflicts of Interest declared: ⊠ None □ Other:					
PROJECT DESCRIPTION Factors Considered* ** Outcome					
Setback/placement of Approved as below structure					



OXFORD HISTORIC PRESERVATION COMMISSION MEETING MINUTES

Paint trim, house garage (white to white)- no reviewed, not	Exterior Construction Materials	5. C, 6.C	
required	Exterior Colors		
History: Previous COA approved	Architectural Details	5. C	
for replacement of internal gutters	Roof (shape/form/materials)	4. C	
due to failure of internal failure of	Doors/Windows/Fenestration	7. C	
channel from facia and soffit, at that	General Form and		
time, all internal gutter on top floor	Proportion		
was replaced	Appurtenant Fixtures		
	Structural Conditions		
	Trees	3. C	

*See attached HPC worksheet for full details of factors considered

** C= Congruent with Historic Aspects for Historic District

NC= Not congruent with Historic Aspects for Historic District

NA= This project does not impact this factor

Discussion:

- 1. Repaint house same color- no review necessary, minor works
- 2. Replace shingles, no review necessary, minor works
- 3. Front Yard landscaping- shape existing bushes, cut back to reasonable height- no review necessary, minor works
- 4. Emergency Roof Repair- where old roof met new roof there was rot, back and side of home. Leaked after storm. Plaster falling inside house.
 - a. Current- Flat tin roof: tin/roof roll and tar
 - b. Proposed- Flat roof: Asphalt shingles and roof roll and tar
 - c. No pictures of current roof provided
 - d. No shingle samples or pictures provided
- 5. Front Porch Repair (decking, columns, trim)- no removal, will be repaired to existing columns, porch tongue and groove to be replaced where needed
 - a. Current: White pine siding, natural tongue and groove decking, white wood columns
 - b. Proposed: White pine siding, natural tongue and groove decking, repair existing columns
 - c. Front view picture of house provided
 - d. No pictures of proposed work provided
- 6. Replace rotting wood siding- replace with wood
 - a. Current: White painted pine siding
 - b. Proposed: White painted pine siding
 - c. No pictures of current siding provided
 - d. No pictures of proposed work or paint sample provided

7. Replacement of Shutters- no review necessary, minor works

Proposed Project Details	Guideline Cited by	Guideline as per HPC	Decision of HPC	
	Applicant			
Emergency Roof Repairs	5.100, 5.102		Applicant to return with	
			requested	
			documentation	
Front Porch Repairs:	7.100, 7.102, 7.103, 7.16,	7.100, 7.102, 7.103, 7.16	Motion to approve: Lisa	
Decking, Columns and Trim	7.107		Schon	
			Second: Lillie	
			Armstrong	
			Approved by HPC	



OXFORD HISTORIC PRESERVATION COMMISSION MEETING MINUTES

	18MAY2023		
Replace Rotting Wood Siding	2.100, 2.102, 2.103, 2.105, 2.106		Applicant to return with requested
			documentation
Replace Shutters	6.104, 6.111	N/A	Minor works, no review necessary
Front Yard Land Scaping	15.101	N/A	Shape existing bushes, cut back to reasonable height Minor works, no review necessary
Repaint House	4.102, 4.103, 4.200, 4.203	N/A	Minor works, no review necessary
Replace Shingles		N/A	Minor works, no review necessary

Deliberation:

1. Columns, Front porch repair- level porch floor, once level reseat exterior of columns

2. Emergency Roof Repair

- a. one section is traditional roof, new addition (r) and back porch are roll roofing- "put it back the way it was"
- b. shingles are generally brought to HPC with specs
- c. current COA does not specify new roofing material
- d. 2 porches and back of house, applicant doesn't know what the replacement materials are
- e. HPC does not know what existing materials are
- f. HPC recommended pictures of existing roof and replacement materials

3. Replace wood siding- like for like

The following options were provided to applicant:

Option A- wait until June meeting,

Option B- applicant gets information then have special meeting (Zoom)

Decision:

Option B for roof- requested applicant bring contractor specs or contractor to Zoom call

COA Application #2

Property Address: 405 College Street, Thomas House- Colonial Revival- 1926 Property Type:
Contributing Residential Non-Contributing Residential Commercial Sworn Stakeholders: James McCloud

HCO Conflicts of Interest declared: ⊠ None □ Other:

PROJECT DESCRIPTION	Factors Considered*	**	Outcome
Paint trim, house garage (white	Setback/placement of	1.C	Approved as below
to white)- no reviewed, not	structure		
required	Exterior Construction	1.C	
History: Previous COA approved	Materials		
for replacement of internal gutters	Exterior Colors		
due to failure of internal failure of	Architectural Details		
channel from facia and soffit, at that	Roof (shape/form/materials)		
time, all internal gutter on top floor	Doors/Windows/Fenestration		
was replaced	General Form and		
	Proportion		
	Appurtenant Fixtures		



OXFORD HISTORIC PRESERVATION COMMISSION MEETING MINUTES

18MAY2023

Structural Conditions	
Trees	

*See attached HPC worksheet for full details of factors considered

** C= Congruent with Historic Aspects for Historic District

NC= Not congruent with Historic Aspects for Historic District

NA= This project does not impact this factor

Discussion:

- Repairing existing rear porch and add ramp to conforms to ADA standards- stained wood to stained wood
- Actually a removal of old deck (not original) and replace deck (extending the deck to meet rise/run of ramp) and add ramp.
- Railings will be replaced (picture provided of Stevens house railings as template)
- Current lattice to be removed and decking material will be used to underpin

Proposed Project Details	Guideline Cited by Applicant	Guideline as per HPC	Decision of HPC
Repair existing rear porch and add a ramp	7.100, 7.103, 7.106	7.100, 7.103, 7.106, 6.106	Motion to approve to: David Quinn Second: Carla Pruett- Dubois Approved by HPC

Deliberation: No further deliberation was required

COA Application #3

Property Address: 214 College Street, Luther Stark House- Colonial Revival- 1904 Property Type: ⊠ Contributing Residential □ Non-Contributing Residential □ Commercial Sworn Stakeholders: Bill Coburn

HCO Conflicts of Interest declared: \boxtimes None \square Other:

PROJECT DESCRIPTION	Factors Considered*	**	Outcome
Paint trim, house garage (white	Setback/placement of		Approved as below
to white)- no reviewed, not	structure		
required	Exterior Construction		
History: Previous COA approved	Materials		
for replacement of internal gutters	Exterior Colors		
due to failure of internal failure of	Architectural Details		
channel from facia and soffit, at that	Roof (shape/form/materials)		
time, all internal gutter on top floor	Doors/Windows/Fenestration		
was replaced	General Form and		
	Proportion		
	Appurtenant Fixtures		
	Structural Conditions		
	Trees	1.C	

*See attached HPC worksheet for full details of factors considered

** C= Congruent with Historic Aspects for Historic District

NC= Not congruent with Historic Aspects for Historic District



Historic Preservation Commission OXFORD HISTORIC PRESERVATION COMMISSION MEETING MINUTES 18MAY2023

NA= This project does not impact this factor

Discussion:

Removal of mature trees (15.207) - certified arborist letter provided

• 17" DBH American elm located at the North East corner of the property line. At some time in the past the elm succumbed to Dutch elm disease. The tree has deteriorated to the point of dropping limbs and large sections with only a slight wind. This tree expands over your neighbors play ground and swing set.

Recommendation: Immediate removal before additional property damage is done or before personal injuries occurs.

• 2.3 - 16" DBH Black walnuts located at the North West corner of the property. The three stems were at one time stump sprouts that all grew together. The close proximity of the three stems has caused included bark at the lower base which has developed into significant decay. Two of the three stems are completely hollow and are on the verge of collapse. All three stems have internal decay in the mid and upper portions of the trunks and have lost most of their strength. There is also a significant volume of dead limbs in the trees and the trees have lost 65 to 70% of their crown mass.

Recommendation: All three stems should be removed. All three stems are on the verge of collapsing into the back lawn.

• 3. 2 – 16" DBH (single base) Black walnut located at North West corner of driveway. The general health of this tree is good but the base splits into co-dominance at 3 feet off the ground. The base of the tree(s) has included bark and the tree(s) are approximately 45 ft tall. The tree(s) are very prone to splitting due to the included bark. The tree(s) also have a significant volume of deadwood which has been dropping on the parking area of vehicles and basket ball court on windy days.

Recommendation: The two main leads could be cabled to help prevent the tree from splitting apart, however the crown will continue to drop dead limbs. Because this location is used for parking and play area, I would suggest removal.

• 4. 22" Red maple located in the South East portion of the back yard. The Red maple is the result of a tree having had the top broken or cut off at sometime in the past. The past action has caused the tree to develop co-dominate tops. The co-dominate stems have significant included bark at their junction which does not allow the two trees to adhere to one another. The vertical seam that is visible at the base of the trees has internal decay. Due to the height of the trees they have a very high probability of splitting during a high wind event or under a heavy snow or ice load. The tree also has large structural roots pushing to the ground surface of the lawn. It appears that the tree is struggling from a lack of oxygen in the soil due to constant pooling of waters after rain events. The tree is also shading the back of the residence which is causing significant mold and decay to the brick foundation.

Recommendation: There are a couple of options with this tree. If you wanted to try and save the tree you would have to hire a qualified arborist to climb the tree and install cabling to reduce the risk of splitting in half along with installing drainage. This might be difficult due to the fact this is the lowest location of the property.

The second option is to remove the tree and grind the stump and elevated roots. The location is very poor for most upland tree species.

• 5. 17" Red maple located on the East side of the driveway at the front of the property. At some point the entire top of the tree broke off leaving only a skeleton of the tree with only four limbs. The tree is being choked and suffocated by English ivy. At this point the tree does not provide any significant shade or value to the landscape.

Recommendation: Remove the tree, grind the stump and replant a low growing tree species that is compatible with the over head utility facilities. This would avoid Duke Energy needing to prune the tree in the future and making is aesthetically displeasing.



Historic Preservation Commission OXFORD HISTORIC PRESERVATION COMMISSION MEETING MINUTES 18MAY2023

Proposed Project Details	Guideline Cited by Applicant	Guideline as per HPC	Decision of HPC
Removal of Mature Trees	15.207	15.207	Motion to approve to: Dickon Housman Second: Lisa Schon Approved by HPC

Deliberation: No further deliberation was required

COA Application #4

Property Address: 200 High Street, Lassiter Mullins House- 1870's

Property Type: ⊠ Contributing Residential □ Non-Contributing Residential □ Commercial Sworn Stakeholders: Emil Malinowski

HCO Conflicts of Interest declared: \boxtimes None \square Other:

PROJECT DESCRIPTION	Factors Considered*	**	Outcome
Paint trim, house garage (white	Setback/placement of		Approved as below
to white)- no reviewed, not	structure		
required	Exterior Construction		
History: Previous COA approved	Materials		
for replacement of internal gutters	Exterior Colors		
due to failure of internal failure of	Architectural Details		
channel from facia and soffit, at that	Roof (shape/form/materials)		
time, all internal gutter on top floor	Doors/Windows/Fenestration		
was replaced	General Form and		
	Proportion		
	Appurtenant Fixtures	1.C	
	Structural Conditions		
	Trees]

*See attached HPC worksheet for full details of factors considered

** C= Congruent with Historic Aspects for Historic District

NC= Not congruent with Historic Aspects for Historic District

NA= This project does not impact this factor

Discussion:

• Installation of metal fence along side of the house- treated wood to aluminum fence

Proposed Project Details	Guideline Cited by Applicant	Guideline as per HPC	Decision of HPC
Install a metal fence along the SW side of property approx. 80 feet long, replacing the hedge row which currently exists in that area. Wood fence on the SW border of the backyard to be moved		14.104, 14.203	Motion to approve: Carla Pruett-Dubois Second: David Quinn Approved by HPC



OXFORD HISTORIC PRESERVATION COMMISSION MEETING MINUTES

18MAY2023

New fence to be installed to		
the be the exact model and		
color already submitted at		
114 High St and 213 High		
St		

Deliberation:

Height of fence determined to be 4 ft

COA Application #5

Property Address: 303 Raleigh Street , Claude Rucker House, 1940

Property Type: ⊠ Contributing Residential □ Non-Contributing Residential □ Commercial Sworn Stakeholders: James Compton

HCO Conflicts of Interest declared: ⊠ None □ Other:

PROJECT DESCRIPTION	Factors Considered*	**	Outcome
Paint trim, house garage (white	Setback/placement of		Approved as below
to white)- no reviewed, not	structure		
required	Exterior Construction		
History: Previous COA approved	Materials		
for replacement of internal gutters	Exterior Colors		
due to failure of internal failure of	Architectural Details		
channel from facia and soffit, at that	Roof (shape/form/materials)		
time, all internal gutter on top floor	Doors/Windows/Fenestration		
was replaced	General Form and		
	Proportion		
	Appurtenant Fixtures	1.C	
	Structural Conditions		
	Trees		

*See attached HPC worksheet for full details of factors considered

** C= Congruent with Historic Aspects for Historic District

NC= Not congruent with Historic Aspects for Historic District

NA= This project does not impact this factor

Discussion:

- Front door lights (16.103)- at the time of the original COA, no lights had been chosen (black metal to black metal)
- Derreck provided picture
- Addendum- shutters on Front St side, shutters to be replaced (same as on front)

Proposed Project Details	Guideline Cited by Applicant	Guideline as per HPC	Decision of HPC
Replace old front door lights	16.103	16.103	Motion to approve to: Jim Brantley Second: Dickon Housman Approved by HPC



OXFORD HISTORIC PRESERVATION COMMISSION MEETING MINUTES 18MAY2023

Deliberation: No further deliberation was required

COA Application #6

Property Address: 414 College Street,

Property Type:
Contributing Residential Non-Contributing Residential Commercial Sworn Stakeholders: Lisa Schon

HCO Conflicts of Interest declared: ⊠ None □ Other:

PROJECT DESCRIPTION	Factors Considered*	**	Outcome
Paint trim, house garage (white	Setback/placement of		NO review required,
to white)- no reviewed, not	structure		minor works based on
required	Exterior Construction		previously approved
History: Previous COA approved	Materials		COA
for replacement of internal gutters	Exterior Colors		
due to failure of internal failure of	Architectural Details		
channel from facia and soffit, at that	Roof (shape/form/materials)		
time, all internal gutter on top floor	Doors/Windows/Fenestration		
was replaced	General Form and		
	Proportion		
	Appurtenant Fixtures		
	Structural Conditions		
	Trees		

*See attached HPC worksheet for full details of factors considered

** C= Congruent with Historic Aspects for Historic District

NC= Not congruent with Historic Aspects for Historic District

NA= This project does not impact this factor

Discussion:

Gravel driveway as opposed to previously approved paved drive, will continue with previous design Decision- like for like- no review needed

Proposed Project Details	Guideline Cited by Applicant	Guideline as per HPC	Decision of HPC
Gravel driveway as option to approved concrete driveway COA, same layout as approved			No approval necessary

Deliberation: No further deliberation was required

New Business				
Торіс	Discussion	Outcome		
Treasurer's Report	Current: \$1,534.88	Dickon requested to review		
	Previously Reported: Previously	donations with Derreck for accuracy		
	reported total was minus	To provide corrected totals		
	adjustments	following review		
	Donations: \$1,529.00 (includes			
	rollover)			



OXFORD HISTORIC PRESERVATION COMMISSION MEETING MINUTES

18MAY2023				
	Remaining Balance after			
	appropriations: \$1,005.88			
Mailbox Signage and playground	Currently, "Lil Library" box is on the	Cheryl who will reach out to		
equipment at home on corner of	curb at front of the house. Current	homeowner with 17.300 as reason		
Raleigh and Henderson	guideline suggested: 17.300 plastic	for removal- HPC agreed		
	sign guideline	, , , , , , , , , , , , , , , , , , ,		
		Playground equipment to be		
	Members do not feel that box is	discussed further in June		
	appropriate.			
	Playground equipment is on the			
	side of the home (Henderson St			
	side), but not on back of home.			
	Home is on a corner lot. Current			
	guideline suggested: 15.303 not felt			
	to cover the playground equipment,			
	15.200 (swimming pools and other			
	recreational amenities) screened by			
Stowardship Award	vegetation – may not cover David has received two members	Mombore agreed to submit votes		
Stewardship Award	votes thus far, encouraged other	Members agreed to submit votes by 24MAY2023		
	members to cast votes via email	by 2400 (12020		
	including 1,2,3 by COB	David to provide figure of what was		
	24MAY2023	spent on plaques last time		
	Carla forwarded David's email to			
	Lillie and Dickon (may not have			
	received initially)			
	One remaining plaque, last			
	purchased two, so we will need to			
	repurchase two new plaques. Took			
	over two months for last plaques to			
	arrive.			
	Demock ourgested that we			
	Derreck suggested that we purchase now while money is in the			
	budget (current budget cycle ends			
	in Jun2023). If we purchase by			
	December, we would have them in			
	time for next years Stewardship			
	Awards.			
College Street Median	Carla updated HPC: Seems to be	Carla to reach out to Mayor Sergent		
	divided thoughts, some feeling that	to get landscaping and lighting		
	there was a median, some don't. Mayer Sergent connected Carla	details		
	with community member, Jimmy	HPC has no jurisdiction in this		
	Crawford, who remembers when	matter		
	median was removed. Carla further			
	spoke with Mayor Sergent			
	spoke with Mayor Sergent			



OXFORD HISTORIC PRESERVATION COMMISSION MEETING MINUTES

18MAY2023			
regarding the requirements for the			
	upcoming College Street Median,		
	which had to be approved by NC		
	DOT, which included:		
	1. City had to seek NC DOT		
	permission for lighting and		
	landscaping of proposed median		
	2. Height requirements for		
	landscaping were taken into		
	consideration for line-of-sight safety		
	3. Mayor Sergent offered to provide		
	details of landscaping and lighting		
	approved by NC DOT		
	HPC has no input into what can or		
	can not be placed into the median		
	as this was dictated by NC DOT		
	City has proposed historic lighting		
	style		
	Landscaping has not been		
	proposed as of yet, per NC DOT,		
	but City has guidelines for proposal		
	requirements		
	Derrock while median is within the		
	Derreck- while median is within the		
	district, we should request details of		
	the planned inclusions of median		
	Timeline for stort of work has not		
	Timeline for start of work has not		
	been released		
	David is on the Granville Gardens		
	Committee so has been pulled into		
	discussions regarding proposed		
	landscaping, as member of		
	Granville Gardens Committee only,		
	not as HPC member. This includes		
	timeline for planting, which needs to		
	have plants in ground by October		
	2023, pending water, drainage,		
	sewer, etc.		
	Bulb outs, new round abouts and		
	new median are subject of these		
	discussions		
	Mr. Coburn voiced concerns with		
	when section of driveway in front of		
	his home will be re-paved. David		
	offered that no deep root system		
L		ıI	



OXFORD HISTORIC PRESERVATION COMMISSION MEETING MINUTES

_	18MAY2023				
landscaping will be planted so					
		nothing to impede the re-paving			
	Meeting Minutes	Carla to continue to provide	Template proposed by Carla		
		minutes until another recording	Lisa to see if template used at her		
		scribe can be identified	place of work is usable		

Old Business				
Торіс	Discussion	Outcome		
Walking Tour Pamphlet & Pocketsite	Dereck scheduled time to provide to Angela last week, however, due to personal reasons, this needed to be rescheduled.	Derreck to provide to Angela 21APR2023		

PARKING LOT

Motion to Adjourn	1 st	2 nd	Outcome
	David Quinn	Lillie Armstrong	HPC agreed, adjourned
			at 7:39 pm

PARKING LOT

- Walking Tour for kids
- Photo Contest Calendar
- Playground equipment- corner of Raleigh and Henderson St

DATE OF NEXT MEETING: 15JUN2023 MINUTES PREPARED BY: Carla Pruett-DuBois